



0,1,2,4,6,7,8,9,11,
15,18,20,22,27



Info Hotline

+49 (0) 5041 998 389

Mon.-Do. 7⁰⁰-20⁰⁰

Fr. 7⁰⁰-17⁰⁰

Paulmann Licht GmbH
31832 Springe / Germany
www.paulmann.com

Art.-Nr.:










60124

60136

60148

(+MA 173)

PDG 04/11



Safety Instructions
Nr. 9

>0.5m = $\square \begin{matrix} 0.5 \\ m \end{matrix}$

Safety Instructions
Nr. 9

>0.5m = $\square \begin{matrix} 0.5 \\ m \end{matrix}$

Safety Instructions
Nr. 9

>0.5m = $\square \begin{matrix} 0.5 \\ m \end{matrix}$



0,1,2,4,6,7,8,9,11,
15,18,20,22,27



Info Hotline



+49 (0) 5041 998 389

Mon.-Do. 7⁰⁰-20⁰⁰

Fr. 7⁰⁰-17⁰⁰

Paulmann Licht GmbH
31832 Springe / Germany
www.paulmann.com


Art.-Nr.:
60124
60136
60148

(+MA 173)


PDG 04/11

D1

Safety Instructions
Nr. 0,1




②




Art.No.
40W 51mm GZ10 800.44

D2

Safety Instructions
Nr. 0,1




②




Art.No.
40W 51mm GZ10 800.44

D3

Safety Instructions
Nr. 0,1



②



Art.No.
40W 51mm GZ10 800.44